



## Temperature/Moisture Statement

Glue Dots® Brand Products are produced using a variety of synthetic, rubber-based adhesives. Extreme heat or cold will have an affect on the adhesive. The optimum air temperature for the application of Glue Dots is between 50° to 90° Fahrenheit. The performance of Glue Dots in other than optimum temperature range will depend largely on the substrates the Glue Dot has been applied to. Glue Dots are impervious to water. Glue Dots must be applied to a dry surface. Humidity/moisture will not have an effect on the adhesive strength/tack of the Glue Dot.

The content provided herein is furnished for informational purposes only and is believed to be accurate as of the date of issue. It is the user's responsibility to determine whether the Glue Dots product is fit for a particular purpose and suitable for user's method of use or application. Glue Dots International makes no warranties, expressed or implied, including, but not limited to, any implied warranty of merchantability or fitness for a particular purpose as a result of sale of products.

Copying and/or downloading of this information are allowed provided that the information is copied in full with no changes unless prior written agreement is obtained from Glue Dots. Glue Dots provides this information in electronic form as a service to its customers. Due to the remote possibility that electronic transfer may have resulted in errors, omissions or alterations in this information, Glue Dots makes no representation as to its completeness or accuracy.